ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0416, W0414, W0418, W0641, W0472, W0645, W0643, W	5th Crs, 3rd Crs Kanaka Lyt, 7th Crs Gramatana, 2nd Crs, 4th Crs, NA, 6th Crs Gramatana	KG Halli AK Colony surrounding area
Segment No.	**Total Length (m)**	
12/C-W0416/S041054	588.12	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	73.35	77.531130	13.061633	77.531802	13.061711	W0410	W0410
2	96.98	77.530143	13.061420	77.531030	13.061536	W0414	W0414
3	113.93	77.529934	13.061604	77.530974	13.061747	W0416	W0416
4	113.74	77.529500	13.061990	77.530542	13.061879	W0418	W0418
5	190.12	77.528919	13.062353	77.530657	13.062126	W0472	W0472

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
improvements to concrete roads in KG Halli AK Colony in Surrounding area in Shettyhalli ward no.12 Shettyhalli Sub Division	10000000	2020
Year	**Type of Work**	**Other Work Type**
2020 - 2021	Others	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender		012-20-000041
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/597/2019-20	30/03/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
10/03/2021	10/03/2022	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Technical Manager (West), KRIDL		9996548.00

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0416, W0414, W0418, W0641,

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಪಿ.ರಸ್ತೆ, ಬೆಂಗಳೂರು

E-Mail ID

No.

044476

Field Inspection Details

Number of Trees	Any Other Information	Name
0		k g Halli AK colony
Date of Inspection	**Remarks**	
20/03/2021		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0416, W0414, W0418, W0641,

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ವಾರ್ಡ್ ನಂ. 12, ಶೆಟ್ಟಿಹಳ್ಳಿ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು.